

Brea
Dept

5c.12.25.

Djak

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *SEA T.S. CREOLE JEFE* Rpt. *NWC* No. *83360*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

1st Long.
 Transverse No. *5174* Depth "d" *✓*
 Framing: Table No. *-* Description *Longitudinal framing*
 Longitudinal No. *23049*
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{19.7}{}$
 Deck Sheerstrake *as approved.*

Revised Rules

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1 (Steel) Carrying Petroleum in Bulk"
 1 SK (Std) + web frames, Longitudinal framing - Brackettes System.
 Bell SB u E+B 50' 149t, Side tanks 180' 2115t, FPT 207t, APT 126t.
 F.K, 8 BH, pt cem, Lloyds A+CP.
 P 73, B 22, F 40. Trunks in wells. Machy aft.

[Signature] *SJR* 16.10.28



© 2020

Lloyd's Register Foundation

11049-0108