

tes and initials of any letters respecting this case.
damage cases where the Surveyor has not made a special damage report he is required to state whether he
ces for this purpose

COPY

COLVILLES LTD., Clydebridge Steel Works, CAMBUSLANG.

Messrs. Brown & Tawse Ltd.,

31st December, 1940

Order No. 23359 8/7/40.

W.O. 16375

t	Cast No.	Descrip- tion.	BREAKING STRESS	Elongation	No. of pieces.	SIZE.
			Tons per Sq. Inch	per cent on 8 ins.		
92	N8434	Steel Boiler Plates	29.0	26.0	1	25'0" x 84" x $\frac{3}{4}$ "

ANALYSIS.

Carbon .18
Silicon .064
Sulphur .038
Phosphorus .023
Manganese .54



© 2020

Lloyd's Register
Foundation

W1163-0132

741 and 4th June 1942 :- Vessel placed in drydock, propeller, outside fastenings, sea covers (open up)
and Pul and shaft (down in) now examined. Windlass & steering engine P.T.O.