

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl Sc. M.S. "KINROSS"

Rpt. Sld

No. 31608

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Longitudinal

Transverse No. 15089.7

Depth "d" 25.06


Framing: ~~Table~~ ~~nom~~ Bulb angle
frames as approved


Description ---

2nd Longitudinal No. 37294

Proportions $\frac{\text{Length}}{\text{Depth}} = 11.07$

Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100A1 with freeboard," as recommended. The Summer freeboard of ~~see~~ from centre of disc verification to top of ~~statutory~~ deck line at ~~form~~ deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

 100A1 with freeboard

1 Dk & Shelter Dk

Cell DB 346' 1174t, MT 1236t, APT 191t

FK, 7 HH (Coll HH to Shelter Dk 6 HH to 2nd Dk), pt. Cem., Lloyd's A & CP

© 2020

Lloyd's Register
Foundation

W1197-0147

Spacing.....