

by Chief Ship Surveyor

Received from Chief Ship Surveyor

24 MAR 1941

VESSEL'S NAME

"BRITISH STRENGTH"

Rpt. Lon

No. 109429

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. 2 held on hull

(The class is subject to 60 fathoms of chain cable being supplied).

The LONDON Surveyors now report the vessel placed in dry dock and the bottom coated.

It is submitted the vessel appears worthy to remain as classed with record of survey 2.41 (subject as above).

100A1)
2.41 Lon) (Subject, etc.)
Carrying petroleum in bulk)

[Signature]
17.3.41



© 2021

Lloyd's Register
Foundation

W12-0079