

W1219-0134

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME *Stl Se. M.V. DUISBURG* Rpt. Name No. *16427*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

St Lang
Transverse No. *13300*

Depth "d" ✓

aming: Table No. ✓ Description *Bulbangle framing as approved*
ngitudinal No. *39424*

Proportions Length = *15.25 5 U.D.*
Depth = *12.00 6 B.D.*

~~Deck~~ Sheerstrake *as approved*

Revised Rules.

Machinery Special.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

*100 A.1. (steel)
2 dks (stl) 3rd dk with 2nd hold. *W.M.A. 11-3-16*
Cell DB 400' 1535t. FPT 75t. APT 46t
FK. 9BH. pt-cum 9ft asph. Laysds A+CP
P+B 375' F 56' well dk.*



© 2021 Lloyd's Register Foundation