

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S. S. "Laurelpark" Report Gls. No. 42124**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey _____ When due _____

✱ 100 A.1 (Steel)

1 DK (Steel)

bell DB. a 63' uE 28' f 124' 5496. FPT 446, APT 426

FK. 4BH. Gen. Lloyds A+CP P 21' B 68' F 29'

Date of Build. 8.22.

M R K. M.
31.8.22.

It is concluded the thickness of upper portion of plating of after peak bulkhead is as approved & not as stated but the Surveyors should be requested to state if this is so.

W1272-0039

© 2021
Lloyd's Register
Foundation