

1

*Alan ... how - Helle*

Sent to Chief Surveyors 12-6-18

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel ss. "Pigua"

Report Phil

No. 2845

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

❖ 100A.1. (Steel)

15K (Steel)

Cell D.B. 254 7026. F.P.T. 1066. a.P.T. 1376

FK. 5BH. Cem. axep. P 29. B 75. F 29.



*2 lines shaft*

© 2021  
13

Lloyd's Register  
Foundation

W1293-0153