

REPORT ON MACHINERY.

No. 43988


Received at London Office

Date of writing Report 27 Aug 1924 When handed in at Local Office 16.9.24 Port of Glasgow
 No. in Survey held at Glasgow Date, First Survey 29.7.24 Last Survey 30.7.1924
 Reg. Book. on the S.S. FORESTGATE (Number of Visits 2) Tons } Gross 1600
 } Net 887
 Master _____ Built at Glasgow By whom built Bardie Currie & Co. Ltd. When built 1924
 Engines made at Grunow By whom made J. G. Kinniburgh & Co. Ltd. when made _____
 Boilers made at _____ By whom made _____ when made _____
 Registered Horse Power _____ Owners _____ Port belonging to _____
 Nom. Horse Power as per Section 28 _____ Is Refrigerating Machinery fitted for cargo purposes _____ Is Electric Light fitted _____

ENGINES, &c.—Description of Engines No. of Cylinders _____ No. of Cranks _____
 Dia. of Cylinders _____ Length of Stroke _____ Revs. per minute _____ Dia. of Screw shaft ^{as per rule} _____ ^{as fitted} _____ Material of screw shaft _____
 Is the screw shaft fitted with a continuous liner the whole length of the stern tube _____ Is the after end of the liner made water tight in the propeller boss _____
 If the liner is in more than one length are the joints burned _____ If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive _____ If two liners are fitted, is the shaft lapped or protected between the liners _____ Length of stern bush _____
 Dia. of Tunnel shaft ^{as per rule} _____ ^{as fitted} _____ Dia. of Crank shaft journals ^{as per rule} _____ ^{as fitted} _____ Dia. of Crank pin _____ Size of Crank webs _____ Dia. of thrust shaft under collars _____ Dia. of screw _____ Pitch of Screw _____ No. of Blades _____ State whether moveable _____ Total surface _____
 No. of Feed pumps _____ Diameter of ditto _____ Stroke _____ Can one be overhauled while the other is at work _____
 No. of Bilge pumps _____ Diameter of ditto _____ Stroke _____ Can one be overhauled while the other is at work _____
 No. of Donkey Engines _____ Sizes of Pumps _____ No. and size of Suctions connected to both Bilge and Donkey pumps _____
 In Engine Room _____ In Holds, &c. _____
 No. of Bilge Injections _____ sizes _____ Connected to condenser, or to circulating pump _____ Is a separate Donkey Suction fitted in Engine room & size _____
 Are all the bilge suction pipes fitted with roses _____ Are the roses in Engine room always accessible _____ Are the sluices on Engine room bulkheads always accessible _____
 Are all connections with the sea direct on the skin of the ship Yes _____ Are they Valves or Cocks Valves and cocks _____
 Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates _____ Are the Discharge Pipes above or below the deep water line _____
 Are they each fitted with a Discharge Valve always accessible on the plating of the vessel _____ Are the Blow Off Cocks fitted with a spigot and brass covering plate Yes _____
 What pipes are carried through the bunkers _____ How are they protected _____
 Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times _____
 Are the Bilge Suction Pipes, Cocks, and Valves arranged so as to prevent any communication between the sea and the bilges _____
 Is the Screw Shaft Tunnel watertight _____ Is it fitted with a watertight door _____ worked from _____

BOILERS, &c.—(Letter for record _____) Manufacturers of Steel
 Total Heating Surface of Boilers _____ Is Forced Draft fitted _____ No. and Description of Boilers _____
 Working Pressure _____ Tested by hydraulic pressure to _____ Date of test _____ No. of Certificate _____
 Can each boiler be worked separately _____ Area of fire grate in each boiler _____ No. and Description of Safety Valves to each boiler _____
 Area of each valve _____ Pressure to which they are adjusted _____ Are they fitted with easing gear _____
 Smallest distance between boilers or uptakes and bunkers or woodwork _____ Mean dia. of boilers _____ Length _____ Material of shell plates _____
 Thickness _____ Range of tensile strength _____ Are the shell plates welded or flanged _____ Descrip. of riveting: cir. seams _____
 long. seams _____ Diameter of rivet holes in long. seams _____ Pitch of rivets _____ Lap of plates or width of butt straps _____
 Per centages of strength of longitudinal joint ^{rivets} _____ ^{plate} _____ Working pressure of shell by rules _____ Size of manhole in shell _____
 Size of compensating ring _____ No. and Description of Furnaces in each boiler _____ Material _____ Outside diameter _____
 Length of plain part ^{top} _____ ^{bottom} _____ Thickness of plates ^{crown} _____ ^{bottom} _____ Description of longitudinal joint _____ No. of strengthening rings _____
 Working pressure of furnace by the rules _____ Combustion chamber plates: Material _____ Thickness: Sides _____ Back _____ Top _____ Bottom _____
 Pitch of stays to ditto: Sides _____ Back _____ Top _____ If stays are fitted with nuts or riveted heads _____ Working pressure by rules _____
 Material of stays _____ Area at smallest part _____ Area supported by each stay _____ Working pressure by rules _____ End plates in steam space: _____
 Material _____ Thickness _____ Pitch of stays _____ How are stays secured _____ Working pressure by rules _____ Material of stays _____
 Area at smallest part _____ Area supported by each stay _____ Working pressure by rules _____ Material of Front plates at bottom _____
 Thickness _____ Material of Lower back plate _____ Thickness _____ Greatest pitch of stays _____ Working pressure of plate by rules _____
 Diameter of tubes _____ Pitch of tubes _____ Material of tube plates _____ Thickness: Front _____ Back _____ Mean pitch of stays _____
 Pitch across wide water spaces _____ Working pressures by rules _____ Girders to Chamber tops: Material _____ Depth and thickness of girder at centre _____ Length as per rule _____ Distance apart _____ Number and pitch of stays in each _____
 Working pressure by rules _____ Steam dome: description of joint to shell _____ % of strength of joint _____
 Diameter _____ Thickness of shell plates _____ Material _____ Description of longitudinal joint _____ Diam. of rivet holes _____
 Pitch of rivets _____ Working pressure of shell by rules _____ Crown plates _____ Thickness _____ How stayed _____

SUPERHEATER. Type _____ Date of Approval of Plan _____ Tested by Hydraulic Pressure to _____
 Date of Test _____ Is a Safety Valve fitted to each Section of the Superheater which can be shut off from the Boiler _____
 Diameter of Safety Valve _____ Pressure to which each is adjusted _____ Is Easing Gear fitted _____



IS A DONKEY BOILER FITTED?

If so, is a report now forwarded?

SPARE GEAR. State the articles supplied:—

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building

During progress of work in shops - - -
During erection on board vessel - - -
Total No. of visits

Is the approved plan of main boiler forwarded herewith

Dates of Examination of principal parts—Cylinders Slides Covers Pistons Rods
Connecting rods Crank shaft Thrust shaft Tunnel shafts Screw shaft Propeller
Stern tube Steam pipes tested Engine and boiler seatings 30-7-24 Engines holding down bolts
Completion of pumping arrangements Boilers fixed Engines tried under steam
Completion of fitting sea connections 30-7-24 Stern tube 30-7-24 Screw shaft and propeller
Main boiler safety valves adjusted Thickness of adjusting washers
Material of Crank shaft Identification Mark on Do. Material of Thrust shaft Identification Mark on Do.
Material of Tunnel shafts Identification Marks on Do. Material of Screw shafts Identification Marks on Do.
Material of Steam Pipes Test pressure
Is an installation fitted for burning oil fuel Is the flash point of the oil to be used over 150°F.
Have the requirements of Section 49 of the Rules been complied with
Is this machinery duplicate of a previous case If so, state name of vessel

General Remarks (State quality of workmanship, opinions as to class, &c.)

Stern Tube, sea cocks and valves fitted, examined and found in order.

The Vessel has proceeded to Greenock, where it is stated, the engines and boilers will be fitted on board

Certificates (if required) to be sent to
The Surveyors are requested not to write on or below the space for Committee's Minute.

Table with 4 columns: Fee type, Amount (£), When applied for, When received.

W. Lane
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW 16 SEP 1924

Assigned See Gen. Rpt. No. 18288



© 2021

Lloyd's Register Foundation