

1

Sent to Chief Surveyors 3. 1. 17

Received from Chief Surveyors

VESSEL'S NAME *Sheels William A. McKenny* Report *L. Ho* No. *1060*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


When due

✱ 100 A-1 (Steel)


2 A's (Steel)

Cell DB 326'. 17116. F.P.T. 3166. A.P.T. 3346.

F.K. 6BH. Cam. axed. P 27' B 117'. F 37'.



The Surveyor should be requested before forwarding the appended plans with the report of the sister vessel to amend same to agree with the report in regard to the 2nd Steel deck which it is reported has been fitted.





© 2021

Lloyd's Register
Foundation

W1300-0157