

Mina

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "LAWINGWORTH"*

Rpt. *Hub*

No. *11194*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *87.3*

Depth "d" *19.12*

Framing: Table No. *3*

Description *Bull angles*

Longitudinal No. *37522*

Proportions Length = *10.77*
Depth

Bridge Deck Sheerstrake as approved
Dunn's letter regarding bulkhead omission attached

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100-A-1. (Steel)

2 Dks (Steel)

Cell 10B a 133' vE 27' f 185' 1374t, ITa 34' 1030t, FPT139t, APT 204E
FK, "Intermediate tween deck bulkhead in after hold dispensed with. See B.H. to Upper deck. One B.H. to second deck only". Cen, bulks Av. CP.

P 37' B 185' F 40'



© 2021
Lloyd's Register
Foundation