

3m. 8.12.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME STEEL S.S. "SEA VICTORY"

Report Grk

No. 17580.

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

❖ 100 A. 1. (steel) "Shelter Deck with Freeboard"

1 Dk (steel) &amp; Shelter Dk (steel)


Cell DB 244' 564 t.

FPT 62 t.

APT 79 t.

FK. 2 BH to Shelter Dk. 4 BH to upper dk.

Cem. Lloyds A+C.P.



2021  
Lloyd's Register  
Foundation  
aes  
12-12-12

W1346-0142

Particulars for Record

Freeboard . . . . .

/ ft. 6 ins.