

2m, 9.9.

1

Sent to Chief Surveyors

31/3/10

Received from Chief Surveyors

VESSEL'S NAME

5th. S.S. "Walnut"

Report

Gls.

No. 28685.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1<sup>st</sup> Entry.

When due

+ 100 A1 ("Steel")

1 Dk (In) "Well deck"

WB = F.P.T. 45t.

BK. 6" 3BH. Lem. Lloyds AVCP Q 80' B 7' F 25' Machinery aft.

RM  
 31/3/10



© 2020

Lloyd's Register  
Foundation

W137-0099