

Im. 12.15.

F.E.

Received by Chief Ship Surveyor 30.10.18

Received from Chief Ship Surveyor

VESSEL'S NAME *Shells Kildonan*

Rpt. *Shel*

No. 30767

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 46.33

Depth "d" 15.0

Framing: Table No. ✓

Description *Bulk angle as approved*

Longitudinal No. 7876.

Proportions Length = 10.3  
Depth =

~~Deck~~ Sheerstrake & other scantlings as approved for the

*A.1. class.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *A.1. (Steel) for Government Service, as reqd.*

*10K (Steel)*

*Cell 573 in E 26' 200'*

*FK. 7BH. pl. Cam. Plyds avcp.*

*M*  
*31.10.18*



© 2021

Lloyd's Register Foundation

01530 - 0050