

1's Name (with late name, if any)

STIAN

Muscantine

No. of Decks with natural light  
No. of Tiers of Beams

To Bridge Dk. Round of Upper

1

Sent to Chief Surveyors 13.5.18

Received from Chief Surveyors

VESSEL'S NAME *Sheelss Muscantine*

Report

No. 14883

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Clasing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

When due

The whole of the bulkheads in this case are extended to the upper dk.

100A.1. (Steel)

2 Dk. (Steel)

Cell DB 322' 995 L. ~~MT 29' 730 L.~~ F.P.T 88' 2. P.T 50 L

F.K. 7 B.H. Cen. area / P 25. B 106 F 37'

Not used as ballast tanks


286-18

13.5.18

21/5/18

s/o

The Surveyors should state whether a deep tank has been fitted in this case & whether the length & capacity of same are as in the vessel's Register



W1539 - 0148

if Machinery is to be fitted aft (Mach. Aft)

ISS dth & thickness

34. 134



Full page marker  
in RBS proof  
28/5/82



© 2021

Lloyd's Register  
Foundation