

No. in R.B.	Vessel's Name and date of Build.	Class of vessel	Surveys due.
9002	ASTER 1920-2.	*100 A.1. Shelter dk with Freeboard 7.21 *LMC 4.20 BS 4.21	Water Tube Boilers due 4.22.
6844	GIGLIO 1917-12.	*100 A.1.-9.20 *LMC 11.18 *NE 11.18 TS 9.20(C.L.)	Special Survey No.1 due 12.21. Two new forward plates to be examined at next dry docking, when bottom also requires to be examined.
7870	PRIMULA 1921-7.	*100 A.1.-10.21 *LMC 6.21. OIL ENGINES.	No Special Survey due. <i>See report received 16 May.</i> On account of damage through bad weather, vessel requires to be again examined and slight leaks made good. After length of counter shaft of the cam shaft (port engine) also requires to be renewed.

22.2.22.



© 2021

Lloyd's Register
Foundation

W1571-0144