

Received by Chief Ship Surveyor 19/8/12

Received from Chief Ship Surveyor _____

VESSEL'S NAME St J's Saint Joseph Rpt. 25 No. 666

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 81.53

Depth "d" 19.94

Framing: Table No. 3 page 15

Description Bull angle as approved

Longitudinal No. 324/8

Proportions Length = 10.10
Depth

Bridge Deck Sheerstrake as per Rule

~~To complete the survey the weather decks~~
~~require to be tested. The wanted Surveyor now~~
~~cables that the survey has been completed~~
M.
22.8.12

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed + 100A-1. (Steel) as recommended, ~~subject to~~
~~the weather decks being tested & found to be satisfactory.~~

+ 100A-1. (Steel) ~~subject to~~

2 D's (Stl)

71 B. Bull 213 a 121 u 24 B 74 f 139 9406 FPT 99t APT 60t
PK. 6 BH. Cum. A & C P PHO B 121 PH3

M

 Lloyd's Register Foundation
22/8/12