

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S. S. " Begum " Report Grk. No. 18025**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry. When due _____

✱ 100A1 (Steel)

2 DKs (Steel - U. pt T.S)

Cell DB. 360' 1181t, DTA 36' 1109t, APT 31t.

FK. "One intermediate BH & one Tween deck BH dispensed with"

5BH to upper DK. 1BH to 2nd DK only.

(Bulkhead letter from burners attached)

Cem. Lloyds A+CP. P 39' B125' F48'

M

RKW

14.9.22.

© 2021

31.4
56.20
257.6

W1624-0006

Lloyd's Register
Foundation