

Report to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "MARY NICKERSON" Report his No. 82151

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Surveyor _____ When due _____

The first lower Anchor is approximately 1 1/2% less in weight than required but as the collective weight of the anchors is in excess of that approved it is submitted this anchor be accepted

- ✦ 100-A-1. (Steel)
- 1 DK (Steel) & Webframes
- FPT 15t, APT 45t
- FK, 3BK, Cur, Plyds Av CP, Q45' B7' F16' Vicky aff

