

COPY.

HULL CERTIFICATE.

Lloyd's Register of Shipping.

Port NATAL,

10th March, 1926.

This is to Certify that I have

examined the Steel S/S "HAMPHOLM" of Osla, $\frac{4480}{2615}$ tons register,
extensive (damage) repairs to bottom plating and floors & frames,


that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and

I have Recommended that she be continued in her present
condition and be assigned fresh Date of Survey 3 - 26, Port Natal,
subject to Stern Frame being further examined first time vessel
redocked at Home port, the leaky rivet in No. 2 Hold to be
made good there, the new anchor shackle supplied here to be
used if considered necessary,

and is fit to carry dry and perishable cargoes.

John Stewart.
Surveyor to Lloyd's Register.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood
that neither the Society nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
entry in the Register Book or other publication of the Society, or for any error or negligence of the Surveyors, or other Officers or Agents of the Society."



© 2019
Lloyd's Register
Foundation
W197-0224