

# Lloyd's Register of Shipping.

Order: 15878  
Post: 112/7

(Report on Vessel No. \_\_\_\_\_ Port \_\_\_\_\_)

No. **3 1 2 3** SHIP ~~FORGINGS~~ CASTINGS.

I have to report that the undermentioned ~~XXXXXX~~ Steel ~~Forgings~~ Castings, manufactured by Messrs. Witkowitz Bergbau & Eisenh. Gew. of **W i t k o w i t z** for the Vessel No. **45**, being built by Messrs. Odense Staalskibsvaerft of **O d e n s e** have been inspected by me as set forth below and found to be, so far as can be seen, **1 stem lower part, sound and free from defects.**

on ~~XXXXXX~~ Castings.

Lloyd's

No. **4516 11147**

**K.13.8.31**

**V i e n n a, 17th August 1931**

*Hans Kolbow*

	STERN FRAME.	RUDDER FRAME.	<b>1 STEM. lower part</b>
Material* ...			<b>Siem. Mart. Steel</b>
Made ...			<b>cast</b>
Sealed ...			<b>annealed</b>
ensions ...			<b>to sketch</b>
ss on Inspection ...			<b>rough machined</b>
When Inspected }			<b>6.8; 13.8.31</b>
CASTINGS.			
on Standard Test Pieces.			
e Test—			
is per square inch ...			<b>29.6 28.8</b>
ension per cent. ...			<b>36.8 38.2</b>
Bending Test—			
ple before fracture ...			<b>120 degr. good</b>
Test—			
ght from ground ...			<b>10'</b>
ering Test—			
made according to Rules } nd found satisfactory ... }			<b>satisfactory</b>

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

ee (if any chargeable) £ : :

To be paid at **VIENNA**

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.