

Do. above
Engine Room ...
Gross Tonnage 4240.31

1m.12.15.

"DIRPHYS"

Theofano

F.E.

Received by Chief Ship Surveyor

24.4.17

Received from Chief Ship Surveyor

VESSEL'S NAME

Shel S.S. Swindon

Rpt.

No. 26966

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

79.

Depth "d"

22.5

Framing: Table No.

3. page 16.

Description

Bulk angle as approved

Longitudinal No.

30810

Proportions

Length

Depth

= 11.47

Bridge Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100 A-1. (Steel) as recommended.

1 DK (Steel)

Ceiling D.B. 338' 1192L. F.P.T. 110L. A.P.T. 77L.

FK. G.B.H. Cam. Legs arc'd. P. 40 B. 244 F 35'

Date of Build 3.17.



© 2021

Lloyd's Register
Foundation

BEAMS, Second Deck, Single Angle, Bulb
Angle, Plate, Tee Bulb, or Channel
Spacing

" " Deck. Material & thickness
Poop Deck Stringer Plate, breadth & thickness