

South America

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl T.S. M/V* "HENRIK AMELN" Rpt. *Cpn* No. *8494*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

12800

Depth "d"

1

Framing: Table No.

✓

Description

*Bulb angle frame**2nd* Longitudinal No.*34800*

Proportions

Length

12.5

Depth =

Deck Sheerstrake

*as approved**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.I. (Steel). Carrying Petroleum in Bulk.

10* (Stl).

Cell D.B. & E 65' 233t, D.T.f 27' 473t, F.P.T. 117t, A.P.T. 38t.

F.K, 10 B.H, pt cem, Lngds A.T.P.

P 91, B. 22', F 50'.

TRUNK IN WELLS

machinery ap.



© 2019

Lloyd's Register
Foundation

W261-0019

14.5.31