

5c.12.25.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl & KIRK POOL* Rpt. *Sld* No. *29760*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

11930

Depth "d"

*25.69*Framing: Table No. *✓*

Description

*Bulb angle frames as approved**2nd*

Longitudinal No.

33512

Proportions

Length

13.75

Depth =

~~Deck~~ Sheerstrake*as approved**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel)

1 D^K (Stl).

Cell D.B. 359' 1344t, F.P.T. 162t, A.P.T. 187t.

F.K. 6 BH, Cen, Lloyds A R.P.

P 30', B 229', F H1'.



© 2020

Lloyd's Register
Foundation