

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME *Stat S. S. GRAY MOUNT*

Rpt. *lth*

No. *16019*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee Report, 24/5/92.)

Transverse No. *33*

Depth "d" *9.34*

Planing: Table No. *3*

Description *Single angle as approved*

Longitudinal No. *4290*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{12.38}{}$

~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed \star 100. A. 1. (Stat) as recommended

1 Dk (Stat) Well Dk

FPT 33t, APT 16t

FK, 38H, Cam Plyths A. C. Q48' B8' F23' Mchly Off

*See lth
3-11-21*

M

HW

28-10-21

The Surveyors should be requested to state whether the record of *ft Asp* *ft Cam* should be made in the Register Book.



© 2020

Lloyd's Register Foundation

W289-0147

HW