

Form No. 1A. WEB FRAMES. FORGINGS or CASTINGS. BULKHEADS. STIFFENERS. PLATING. RIVETING. STRAKES. BUTTS. FRAMES extend in one length from C.K. to Deck. REVERSED FRAMES on floors and frames extend from Side to Side. MASTS, SPARS, &c. LOWER MASTS. Fore Main Mizzen. Rigging, Material and Size, Shrouds. Sails. Topmasts, Yards and Remainder of Spars.

EQUIPMENT No. 4740. LETTER d. ANCHORS. TONNAGE U.D.K. OR PLATING No. FOR TRAWLERS. 55197 55196. 35577. Particulars of Drop Test of Cast Steel Anchors, viz.: Weight, Surveyor's Initials, Number of Certificate, Date of Test. CHAIN CABLES. HAWSERS AND WARPS. Boats. Pumps, Number. Windlass is Steam and hand. Engine Room Skylights. Coal Bunker Openings. Number of Scuppers. Ceiling in Holds. Cargo Hatchways. State size No. 1 Hatch. Number of Web Plates. Bulwarks, height above deck. The foregoing is a correct description. Builder's Signature (here only). Correspondence. Workmanship. Is the riveted work properly closed? Are the liners between the frames and plates solid single pieces? Are the butts of plating, stringers, &c., properly shifted and lapped? Have all the upper and weather decks been tested as required by the Rules (Sec. 26, par. 20)? Have all the gutterways been tested as required by the Rules (Sec. 26, par. 20)? General Remarks (State quality of workmanship, &c.). This Vessel has been built in accordance with the approved plans, and in general conformity with the Rules. The workmanship and materials are good. 7. Approved plans are enclosed herewith for reference, which please return for dealing with Sister Vessel No. 127, now completing. 2. Findings Reports attached hereto. This is a Sister Vessel to the S.S. "Solway Firth" and "Brunton", built Reports No. 15921 & 15945. The Surveyor should state the Number of Report and Name of any Sister Vessel. Plans to be forwarded with F.E. Report showing vessel as built. Freeboard. The amount of Entry Fee. Special Survey Fee. Travelling Expenses, if any. State whether the Vessel has been built under Special Survey. I am of opinion this Vessel should be Classed. With, or without Freeboard, as condition of Class. Committee's Minute. Character assigned. TUE. NOV. 11 1921. + 1000. Lloyd's at C.P. + Lmcl. 10.21. 2020. Lloyd's Register Foundation.

GENERAL REMARKS—(continued).

STEM

3 3
1 1 .50 | .15 62.34 4.07 51.35 Sing. R. 2.24
1 1 .40 | .20 51.35 7.27 44.22
1 1 .40 | .20 51.35 7.27 44.22

Single pit with built in
80

Yes.

Clear beneath process.
S. White Stn. Dominion St. Co. O. Broadmore Co.
S. White Stn.

Yes.

None in hold.

Yes.

Ordinary.

35	52	43	48	35	52	Double	43	34	23	Tide	36	34	✓	✓	9	24
44	375	375	375	44	36	Sing.	36	✓	✓	Double	FL	34	258	✓	✓	5
54	✓	✓	✓	54	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
50	✓	✓	✓	50	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
56	✓	✓	✓	56	✓	Double	34	43	✓	✓	✓	✓	✓	✓	✓	✓
58	50	83	✓	58	46	Double	43	✓	✓	✓	✓	✓	✓	✓	✓	✓
45	40	✓	✓	45	38	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ✓ ft., R.Q.D. 48.25 ft., Bridge 8.08 ft., Forecastle 22.55 ft.
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as it should appear in the Register Book) One Dk. (Stl.)

Official No. 145423; Signal Letters

State if Machinery is fitted aft Machy. aft.

How are the surfaces preserved from oxidation? Inside Cement, Putty & Paint.

Outside Paint.

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors. No cell B.D.

Where Fitted.	Length. Feet.	Water Capacity. Tons.	Where Fitted.	Length. Feet.	Water Capacity. Tons.
Double bottom, aft,	✓	✓	Fore peak tank,	16.00	33
Double bottom, under Engines and Boilers,	✓	✓	After peak tank,	8.00	16
Double bottom, if under Engines only,	✓	✓	Deep tank, aft,	✓	✓
Double bottom, if under Boilers only,	✓	✓	Deep tank, forward,	✓	✓
Double bottom, forward,	✓	✓	Other tanks, if fitted,	✓	✓
Total capacity of double bottom			(If necessary, furnish further information by sketch.)		

* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules.

Yes. Satisfactory.

Order for Special Survey No. 1094.

Date 16-1-20.

No. 126. in builder's yard.

DATES of Surveys held while building

1920: Mar. 29, 31. Ap. 8, 14, 22, 28. May, 3, 10, 13, 18, 19. June 3, 10, 14, 16, 30. Aug. 16. Sep. 7, 14, 16, 23, 27. Oct. 6, 14, 18, 21, 28.
Nov. 2, 9, 16, 18, 23, 25, 30. Dec. 1, 7, 9, 13, 16, 20, 28, 30.
1921: Jan. 11, 13, 18, 21, 27, 31. Feb. 2, 8, 7, 9, 16, 23, 25.
Mar. 2, 7, 17, 22, 28. Ap. 9, 26. May, 5, 12, 20, 25, 28. June, 1, 6, 18, 20, 24. July, 5, 12, 19. Aug. 9, 20. Sep. 8, 30.
Oct. 11, 17, 19.

Total No. of Visits

82

Surveyor's Signature

Robt. Sheetham, and for J. R. Henderson.