

3885

~~7082~~

APPLEBY IRON COMPANY, LTD., SCUNTHORPE, LINCS.

 Customer Paul & McLeod. GLASGOW. Date 27.1.30

 Builder D. & W. Henderson & Co., Ltd.,

 Mark or Job No. _____ **Boiler** TENSILE—Tons per sq. inch 28/32 Batch No. 7/11

 Customer's Order No. A263 REQUIREMENTS ELONGATION—per cent. _____ Inspection _____


 Works Order No. 5624J259 CONTRACTION OF AREA—per cent. _____ ELASTIC LIMIT—
per sq. inch or per cent. _____ Lloyds

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

901M

Initials of Test House Manager _____

PLATE No.	CAST MARK	POSITION	TEST RESULTS	PLATE MARK	PIECES CUT	SIZE	THICKNESS	APPROX. WEIGHT				REMARKS.
								T.	c.	qr.	lbs.	
B432	6747			OB	2	10'0 $\frac{1}{2}$ " x 18 $\frac{1}{4}$ "	$\frac{7}{8}$ "	9	2	26	S	
(431)	-			G	3	9'3" x 36"	11/16"	1	0	3	10	
432	-			901	1	6'3" x 51"	$\frac{7}{8}$ "	8	1	24	$\frac{1}{2}$ of This Plate	
(439)	6753			S	1	21'4 $\frac{3}{4}$ " x 12 0 $\frac{1}{2}$ "	1 $\frac{1}{8}$ "	4	8	0	2	
(442)	-			S	1	- -	-	4	8	0	2	
(455)	6752			901	1	4'6" x 42"	1 $\frac{5}{8}$ "	10	0	4	$\frac{1}{2}$ of This Plate	



© 2020

 Lloyd's Register
Foundation

W3-0093