

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME *St S "OIL TRADER"* Rpt. *huc* No. *82125*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


*1st Long*Transverse No. *12743*Depth "d" *20'*Framing: Table No. *✓*Description *Longitudinal framing**2nd* Longitudinal No. *34542*Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.19}{1}$

Deck Sheerstrake

*as approved**Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100A.1. (Steel). Carrying Petroleum in Bulk
 2 Dth (Stl). Web Frames. Longitudinal Framing.
 Cell D.B. & E.B. 62' 186t, D.T. & 30' 122t, F.P.T. 77t, A.P.T. 282t
 F.K., 15 B.H. (10 B.H. to upper Dth 5 B.H. to 2nd Dth). pt cm. Clayds ArCP.
 P 106', B 26', F 39'. Machy aft.



© 2020

Lloyd's Register
Foundation

W350-0120