

Are all the bilge suction pipes fitted with roses

No Are the roses in Engine room always accessible

No Are the sluices on Engine room

s/s "Falaree."

Leith 15370.

It is submitted the Leith Surveyors should be requested to return the Glasgow Report No. 37495 on the boiler of this vessel, forwarded to them on the 1st March & not forwarded with their report on 22nd inst.

AWD.

23/4/18.

W37-0147

ch boiler 2 opening valves

Area of each valve

Pressure to which they are adjusted

Are

|||||

7-25

$$\begin{array}{r} 100 \\ .175 \\ \hline .275 \end{array}$$
$$\begin{array}{r} 628 \\ 275 \\ \hline 353 \\ \hline \end{array}$$


© 2019

Lloyd's Register
Foundation