

Condition of Class.

NAME OF VESSEL. **m.s. "DUNVEGAN CASTLE"**.....


Extract from Freeboard Verification of marking form received
from..... **Belfast** Surveyors dated... **31.7.36**...

Moulded depth	43	ft. 6	ins.
Corresponding draught	28	ft. 2	ins.
Moulded depth as shewn on draught sheet	43	ft. 6 $\frac{1}{4}$	ins.
Tropical freeboard	14	ft. 11 $\frac{3}{4}$	ins.
Summer "	15	ft. 6 $\frac{3}{4}$	ins.
Winter "	16	ft. 1 $\frac{3}{4}$	ins.
Winter North Atlantic freeboard	-	ft. -	ins.
Fresh water allowance	7 $\frac{1}{4}$	ins.	

Marked from ~~wood~~/steel upper deck.

Checked by.....

Date... **4.9.36**...



© 2020

Lloyd's Register
Foundation

W383 - 0028

Angles

Poop Deck, Angle, [] or []