

1

RETAIN

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stal S. S. "GRACIA"*Report *JK*No. *17847***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

The Downton pump has been dispensed with for the present but it is concluded the Owners are agreeable to fit same when required. Copy of Owners letter re omission of tween deck bulkhead, attached

✱ 100.A-1. (Stal)

2 Dks (Stal)

Cell IB 355' 1123t, FPT 89t, APT 46t

FK, Intermediate tween DK bulkhead dispensed with, 6 BH to upper DK
2 BH to 2nd DK only, ft Cen, Lloyds Av CP, P35', B151' F46'

"Camping oil fuel F.P above 150°F in deep tank aft"

W398-0042



© 2020

18.7.21

Lloyd's Register
Foundation