

Lloyd's Register of Shipping.

(Report on Machinery, No. 10517 Port MIDDLEBURY)

No. F13211. ENGINE ~~FORGINGS OR~~ CASTINGS.

I have to report that the ~~Iron or Steel Forgings or~~ Castings, as herein described, manufactured by The Stockton Steel Foundry Co Ltd of Stockton-on-Tees for the Engines No. 1906 being constructed by Messrs Blain & Co Ltd of Stockton-on-Tees for the Ship No. _____, being built by _____ of _____

have been inspected by me as set forth below, and found to be, so far as can be seen, Sound

Mark on ~~Forgings or~~ Castings.

Lloyd's

No. 603

604 608

Charles E. Wilks

December 9th 1918

	CRANK SHAFT.	STRAIGHT SHAFTING.		
		THRUST SHAFT.	INTERMEDIATE SHAFTS.	PROPELLER SHAFT.
Material* ...	<u>Tropenas Steel</u>			<u>Wight</u>
How made ...	<u>Cast</u>			
Dimensions ...	<u>✓</u>	<u>2 Top. Half bottom ends No. 603, 4 = 5 - 0 - 6</u>		
Progress on Inspection }	<u>Rough</u>	<u>1 Bolt " " " " 608 = 3 - 2 - 6</u>		
Tests on Standard Test Pieces.				
Tensile Test—				
Tons per square inch ...	<u>✓</u>			
Extension per cent ...	<u>✓</u>			
Cold Bending Test—	<u>✓</u>			
Angle before fracture ...				
Dates when Inspected	<u>Dec 6th 19th 1918</u>			

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

Dropped & Hammered

Fee (if any chargeable) £

To be paid at

* If of iron, state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.



© 2019

Lloyd's Register
Foundation

W40-0136