

## Condition of Class.

NAME OF VESSEL....."HYLTON".....

Extract from Freeboard Verification of marking form received  
from.....Sunderland.....Surveyors dated...6.1.37....

Moulded depth	28	ft.	4	ins.
Corresponding draught	25	ft.	3	ins.
Moulded depth as shewn on draught sheet	28	ft.	4 $\frac{1}{2}$	ins.
Tropical freeboard	2	ft.	10 $\frac{1}{4}$	ins.
Summer "	3	ft.	4 $\frac{1}{2}$	ins.
Winter "	3	ft.	10 $\frac{3}{4}$	ins.
Winter North Atlantic freeboard	-	ft.	-	ins.
Fresh water allowance	6 $\frac{3}{4}$	ins.		

Marked from ~~wood~~/steel upper deck.Checked by...*km*...

Date...27.1.37...



© 2020

Lloyd's Register  
Foundation

W404-0030