

1

Sent to Chief Surveyors.....

Received from Chief Surveyors..... 1st June 1942

VESSEL'S NAME ..... HOEGH MERCHANT ..... REPORT ..... S.Fo. .... No. 8482 .....

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey ..... Docking. .... ~~When due~~ .....

Subject to permanent repairs to (cracked) shell plate

No.2 in 5th strake below sheerstrake (p.s.) at the

first opportunity.

Wals  
29.5.42



© 2020

Lloyd's Register  
Foundation

W42-0155