

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 24th Feb 42 When handed in at Local Office 25th Feb 42 Port of NEWCASTLE  
 No. in Survey held at Lough Shields Date, First Survey 11th Feb. 2 Last Survey 13th Feb 1942  
 Reg. Book. "HARPAGON" (No. of Visits 2)  
24884 on the Wood, Iron or Steel By whom Lithgow & Co. When 1935  
 TONNAGE Built at Port Glasgow Owners National S.S. Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book).  
 No. 5719 GROSS 5026 UNDER DK. 5378 NET 5378 Managers J. & B. Harrison Ltd. Port belonging to London  
 Vessel. Built at Surveyed Afloat or in Dry Dock? Superior Nausea of Dock Middle D.R. Co. Ltd. Destined Voyage

Owner's Name J. & B. Harrison Ltd. Mgr. Address 66, Mark Lane, London, E.C.3. Now a  
 Case previously before Date Particulars of Classification  
 Classing Committee. Last Minute +100 A1. +LMC. 9.39  
with fuel. BS. 8.41.  
2.42. TS. 10.38 No. 100207  
SS. No. 1-39.  
Fitted for oil fuel 6.35 ation of the Classing Committee.  
 Date of Casualty 19th April, 1942 Cause or causes of such repairs, and also  
 Précis of particulars of Casualty Sunk by internal explosion about Committee may have all the salient points

miles N.W. of Bermuda on the 19th April, 1942. ated shell plate No. 3 in  
th at the Owners' convenience,  
ide in way of Nos. 1 &  
being permanently  
ng repaired at the  
s in Nos. 1 & 2  
at the next dry  
1st & 2nd strakes  
repaired

R SECTION

ON (which must be inserted  
Book & Supplement)

Machinery and Boiler  
(including date of S.D., if any).

LMC 9.39  
BS 8.41  
CL 10.38

2 6.35

F

is Closed. (W.E.)

written Surveyor.

5 - Feb. 1942)

b. 1942, whilst

ed & recoated  
me to the


d by the

P.T.O.

Suggested Record

Date of Committee

Committee's Minute



© 2020

Lloyd's Register  
Foundation

W43-0112

Fitted for oil fuel

W43-0114

Is Certificate required? If so, to be sent to