

FREBOARD VERIFICATION FORM FOR STEAMERS.

DECK.

DARD REPORT on the "Sea Rambler"

It is submitted the Off. Surveyor be referred to this Rpt. 8 dated 24.2.32, and requested to state if the entry thereon means that the freeboards were not verified or that they were no longer marked on the vessel's sides.

WJ

J. J. 32



© 2020

Lloyd's Register Foundation

W463-0243

E. - The of beam be report the full of vesse unware.

1 -

7 1/4
5 1/2
4 3/4
11 1/2
6 3/4
4 3/4

✓

1 1/2
3/4

✓