


N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.


CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

Deck, 6.  
183. 5.2  
No. 1 - 32

It is submitted the Calcutta Surveyors might be authorised to undertake the duties desired if requested by the Owners, or their Representatives, or with their consent.

9. 8. 35. 

board (if assi  
ship and now  
whom?



© 2020

Lloyd's Register  
Foundation

Wh66-0014

9-AUG1935

Assd. 9  
LONDON

VV LN

992 CALCUTTA 36 9 1440

49