

5c.11.36.

1E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME Realf

Rpt. Ann. No. 1577

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/22.)


Type of Engine Oil Engines 2 SCDA.
6 Cy. 23 5/8" - 43 5/16" 1162 NHP.

If Boilers fitted with forced draught No main boilers
Tail Shaft. If fitted with a continuous liner Yes
If fitted with an outside gland of approved type No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 5.37.

2 DB 171 M.

JH
2/6/37.



13

RETAIN



© 2020

Lloyd's Register Foundation

1st Bowe
2nd ,,
3rd ,,
ORD in
n the Po
informa
: Sign
ER BA
a.
ad Boile

raike Horse
Tom. Horse P
for whi
NGIN
a pressur
hicated P
earings,
ns per m
Shaft, d
Shaft
Shaft, di
Liners,
boss
er does n
ners are
No 1
er, dia. 5
of reve
d. T
cting ma
Water
2. "
amps w
connected
ling wa
nts.....
Pumps,
ndepende
To. and s
cc. 2-
dent P
be Bilge
easily a
ea Com
ized suffi
ch filled
s pass t
s pass t
ipes, Co
ngemen
nt to an
vessel, a
Air Com