

1

Parkhill

Sent to Chief Surveyors 13. 10. 15

Received from Chief Surveyors

VESSEL'S NAME Steel S. S. wheatsheaf Report Gls No. 35489

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due

✕ 100 A.I. (Steel)

1 DK (Stl) "well dk."

W.B. = Gell DB 82', 102 t, F.P.T. 34 t A.P.T. 30 t.

B.K. 8", 3 B.H. Cam. Lloyd's A + C.P. Q. 96', B. 11', F. 24'

mchly aft.

M. A.P.
13.10.15



© 2020

Lloyd's Register
Foundation

W481-0114

BEAMS, AND OTHER
Bulb A
Angles
Spacing