

# FREEBOARD VERIFICATION FORM FOR STEAMERS CARRYING TIMBER DECK CARGOES.

When received in London Office

*Gothenborg*  
*Atlanten*  
7782

No.

No. in Reg. Book

of Registry (For Foreign Ships)

r Steel

State whether Classed by Lloyd's Register *+100-A-1*

of Owners

Date of Verification

I have to report that the Freeboards as given below, assigned by the  
Committee to this ship, have been correctly marked on the ship's sides, in  
accordance with the printed instructions:—

CARGO AND PASSENGER SHIPS.

Freeboard amidships from top of deck line, *W*/steel deck.

Tropical Fresh Water	ft. <i>1187</i> ins.
Fresh Water	ft. <i>1289</i> ins.
Tropical ~	ft. <i>1327</i> ins.
Summer	ft. <i>1429</i> ins.
Winter	ft. <i>1531</i> ins.
Winter North Atlantic	ft. <i>✓</i> ins.

From centre of disc.

<i>m/m</i>	ins. above
<i>242</i>	ins. above
<i>140</i>	ins. above
<i>102</i>	ins. above
<i>102</i>	ins. below
<i>✓</i>	ins. below

CARRYING TIMBER DECK CARGOES.

Freeboard amidships from top of deck line, *W*/steel deck.

Tropical Fresh Water Timber	ft. <i>811</i> ins.
Fresh Water Timber	ft. <i>954</i> ins.
Tropical Timber	ft. <i>954</i> ins.
Summer Timber	ft. <i>1097</i> ins.
Winter Timber	ft. <i>1288</i> ins.
Winter North Atlantic Timber	ft. <i>1568</i> ins.

From centre of disc.

<i>m/m</i>	ins. above
<i>618</i>	ins. above
<i>475</i>	ins. above
<i>475</i>	ins. above
<i>332</i>	ins. above
<i>141</i>	ins. { above
<i>139</i>	ins. { below

in Summer Draught corresponding to the freeboard assigned as shown on  
Builders' Displacement Scales:—

*once for fresh water for all freeboard 140 m/m* Surveyor.

(filled up in London Office.)

at No.

Date of Committee's Minute

for Record	Moulded Depth	26 ft. 1 ins.
Register Book.	Freeboard	4 ft. 8 1/4 ins.
	Corresponding Draught	21 ft. 7 ins.

as compared and found correct by *WMB* Date

id?

Form for Certificate

*Swedish form D*

ns

Date

ificate written

*18.3.32*

Noted for posting

W490-0194

© 2020  
Lloyd's Register  
Foundation