

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S. Motor Vessel LINNELL*Report *Yes*

No. 41636

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

✱ 100-A-1. (Steel) Shelter Deck with foreboard

2 Dks (Steel) 2 Shelter Dk (Steel)

All DB 353' 1108t, ITa 42' 804t, FPT 120t, APT 79t

FK, 7BH to Shelter Dk 1BH to Upper Dk, pt Cen, Lugs as Ar &amp; C

F 37' on Shelter Dk

© 2021



Lloyd's Register  
w 500-0065  
Foundation