

8. For the information of Surveyors and the Committee only. JUN 18 1937

Received at _____ Office _____ 10

Lloyd's Register of Shipping.

(Report on Vessel No. 95156 Port Newcastle)

No. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~ Castings, manufactured by Messrs E. Japling & Sons Ltd of Sunderland for the Vessel S.S. "KIRKWOOD", being built by Messrs John Redhead & Sons Ltd of South Shields have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

on Forgings or Castings.

Lloyd's
No. 9495
25.1.6.35

D.E. Galleford

1-5'0" QUADRANT. Sunderland. 4.6.37

	STERN FRAME.	RUDDER FRAME.	STEM.
Material*		<u>Steel Casting</u>	
made		<u>Electric Furnace.</u>	
annealed		<u>Heat treated</u>	
Dimensions		<u>As per pattern</u>	
Process on Inspection		<u>Rough dressed</u>	
When Inspected		<u>1/6/1937</u>	
CASTINGS.		<u>TEST N° 116</u>	
Tests on Standard Test Pieces.			
Tensile Test—		<u>31.0</u>	
Stress per square inch		<u>26</u>	
Elongation per cent. ...		<u>120°</u>	
Bending Test—		<u>8ft</u>	
Angle before fracture		<u>Yes</u>	
Distance from ground ...			
Hardening Test—			
Made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.


C. Q. LBS.
22. 1. 22.

Fee (if any chargeable) £ Monthly etc

To be paid at _____

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

on, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2021

Lloyd's Register

W51-0120

012

Surveyor