

11868

2(a).

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ^{AND} OR PASSENGER SHIPS.

When received in London Office

Genoa "Cabo Raulto Tome"

No. in Reg. Book *59065*

Registry (For Foreign Ships)

Reville

Steel *Steel*

State whether Classed by Lloyd's Register *+100 P.I. with freeboard.*

Owners Date of Verification

I have to report that the Freeboards as given below, assigned by the
tee to this ship, have been correctly marked on the ship's sides, in
ce with the printed instructions:—

FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE,		FROM CENTRE OF DISC.	
<i>Composition on V</i> / STEEL DECK.			
tropical Fresh Water	<i>3288</i> ^{1/4}	ft. = <i>129.48</i> ins.	<i>336</i> ^{1/4} = <i>13.20</i> ins. above
resh Water	<i>3449</i> ^{1/4}	ft. = <i>135.80</i> ins.	<i>175</i> ^{1/4} = <i>6.88</i> ins. above
ropical	<i>3463</i> ^{1/4}	ft. = <i>136.36</i> ins.	<i>161</i> ^{1/4} = <i>6.32</i> ins. above
ummer	<i>3624</i> ^{1/4}	ft. = <i>142.68</i> ins.	
inter	<i>3785</i> ^{1/4}	ft. = <i>149.00</i> ins.	<i>161</i> ^{1/4} = <i>6.32</i> ins. below
inter North Atlantic	<i>✓</i> <i>✓</i>	ft. <i>✓</i> ins. <i>✓</i>	<i>✓</i> <i>✓</i> ins. below

a Summer Draught corresponding to the freeboard assigned as shown on

ers' Displacement Scales:—

Clearance for Fresh Water
in all freeboards = 175 ^{1/4} = 6.88 ^{1/4}

Surveyor.

(to be filled up in London Office.)

ent No. *34063* Date of Committee's Minute

ars for Record gister Book.	Moulded Depth	ft.	ins.
	Freeboard	ft.	ins.
	Corresponding Draught	ft.	ins.

ards compared and found correct by

Date *11.11.36*

aid ?

Form for Certificate

Spanish *31/12/1936*

ons

Date

te written

15. 11. 36

Noted for posting

W513-0069

Lloyd's Register
Foundation