

Received from Chief Surveyors

Sent to Chief Surveyors

VESSEL'S NAME Stl. Sc. "HARMANTEH" Report Grk No. 19426

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinet summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry. When due _____

✠ 100 A1 (Steel).

1 Dk. (Stl)

Cell D.B. a + u E 158' f 189' 1397t, F.P.T. 167t, A.P.T. 240t.

F.K, 7 B.H, Cem, Lloyds A + C.P.

P 41', B 270', F 38.

 © 2020 E.H.
6-2-31
Lloyd's Register
Fou 523-0189

RETAIN



© 2020

Lloyd's Register
Foundation

length
breadth
depth
AMES
"
"
DE FR
Frame
"
KEEP /
level
Depth
Frame
"
"
Framin
Diamet
State in
W. A.
NTING
RENG
WA