

No. 18/31
29960FREEBOARD VERIFICATION FORM
FOR ORDINARY CARGO ^{AND}_{OR} PASSENGER SHIPS.

When received in London Office

31 MAR 1933

Port AntwerpName "GASTELU"Official No. ✓No. in Reg. Book 62722Port of Registry (For Foreign Ships) San SebastianMaterial or Steel Steel State whether Classed by Lloyd's Register +100 A1Name of Owners Ciudad de Guayaquil Date of Verification 29th March 1933

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, WOOD /STEEL DECK.		FROM CENTRE OF DISC.
Tropical Fresh Water	✓ ft. 991 ^{mm.} ins.	254. ^{mm.} ins. above
Fresh Water	✓ ft. 1.073 ^{mm.} ins.	152. ^{mm.} ins. above
Tropical	✓ ft. 1.123 ^{mm.} ins.	102. ^{mm.} ins. above
Summer	✓ ft. 1.225 ^{mm.} ins.	
Winter	✓ ft. 1.339 ^{mm.} ins.	114. ^{mm.} ins. below
Winter North Atlantic	ft. - ^{mm.} ins.	- ins. below

Minimum Summer Draught corresponding to the freeboard assigned as shown on Builders' Displacement Scales:—

p. Dec. 60. 30/3/32

[Signature]
Surveyor.

(To be filled up in London Office.)

Document No. 29960 Date of Committee's Minute 30/1/33

Particulars for Record { Moulded Depth 25 ft. 8 ins. ✓
Register Book. { Freeboard 4 ft. 0 1/4 ins.
Corresponding Draught 21 ft. 10 ins. ✓

Freeboards compared and found correct by WMB Date 31/3/33Fee paid? Form for Certificate Spanish - 31/12/1937

Instructions Date

Certificate written 28/3/33 Noted for posting ✓

WS28-0208

Lloyd's Register
Foundation