

Working Pressure

Tested by hydraulic pressure to

Date of test

No. of Ce

Can each boiler be worked separately

Area of fire grate in each boiler

No. and De

W558-0032

Are they

s/s. "Foresthill"

Grk 18327.

It is submitted the Greenock Surveyors should be asked to state whether they are correct in reporting that the diameter of the propeller of this vessel is 13 feet & the pitch 12 feet, whereas in the sister vessel "Forestgate" the diameter is reported as 12 feet & the pitch 13 feet.

Lr. Gls 7. 1. 25.

13 ft dia. 12 ft pitch  
see Gls. ltr 10/1/25

4/12/24

Diameter of tubes

Pitch of tubes

Material of tube plates

Thickness: Front

Back

Pitch across wide water spaces

Working pressures by rules

Girders to Chamber tops: Ma