

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

S. S. "Grouant Rose"

Report

*Gls.*No. *44084***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1st Entry

When due

Old Rules✦ *100A1 (Steel)**1 DK. (stl.) "Well deck"**Cell D.B. f 136' Hst. F.P.T. 80t. A.P.T. 34t.**F.K. 3B.H. Cam. Sloyds A.C.P. Q. 123' B. 12' F. 74.**"Mchy. Aft."**MS74-0083*

© 2011
 73-10-744
 Lloyd's Register
 Foundation