

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME *St S* "ENNISKILLEN" Rpt. *Abn.* No. *14641*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Long
Transverse No. *1656*

Depth "d" _____

aming: Table No. *✓*Description *angle frame as approved*ngitudinal No. *5002*Proportions Length *11.50*
Depth = _____~~Deck~~ Sheerstrake*as approved**Revised Rules*

This vessel appears to have been built in accordance with the
rules and the approved plans, and it is submitted she is eligible to
be classed

✱ 100 A. I. (Steel).

1 D* (Stl).

Cell D.B. 79' 92t, F.P.T. 30t, A.P.T. 6t.

F.K. 3B.H, Cem, Lloyds A.C.P.

Q 44', B 9', F 23'. machy apr.



© 2021

Lloyd's Register
Foundation

WS77-0257