

Rpt. 12.

COPY.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port ROTTERDAM. When received in London Office  
 Vessel's Name S. S. "OOSTKERK", ex "AAGTEKERK".  
 Official No. \_\_\_\_\_ No. in Reg. Book \_\_\_\_\_  
 Port of Registry (For Foreign Vessels) The Hague,  
~~Iron or~~ Steel Stm. State whether Classed by Lloyd's Register Yes.  
 Name of Owners \_\_\_\_\_ Date of Verification 30. 1. 22.

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	8	ft.	3	ins.	
From centre of disc to top of statutory deck line at awning or part-awning deck	--	ft.	--	ins.	
Fresh Water line above centre of disc			7	ins.	
Indian Summer line above centre of disc			6 1/2	ins.	
Winter line below centre of disc			6 1/2	ins.	
Winter North Atlantic line below centre of disc			--	ins.	
Distance between the top of statutory deck line on vessel's side and the intersec- tion of the continuation of upper side of <b>Steel</b> <del>wood or iron</del> deck with the vessel's side	}	at <del>main, spar or</del> upper dk.		1 3/4	ins.
		at awning or pt.-awning dk.		--	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.


(Signed) R. LEEUWENBURG. Surveyor.

(To be filled up in London Office.)

Statement No. \_\_\_\_\_ Date of Committee's Minute 8. 12. 21.  
 Particulars for record in Register Book {  
     Moulded Depth . . . . . 35 ft. 6 ins.  
     Freeboard . . . . . 8 ft. 3 ins.  
     Corresponding Draught 27 ft. 8 ins.

Freeboards compared and found correct by \_\_\_\_\_ Date \_\_\_\_\_  
 Is fee paid? \_\_\_\_\_ Form for Certificate \_\_\_\_\_  
 Instructions \_\_\_\_\_ Date \_\_\_\_\_  
 Certificate written \_\_\_\_\_ Noted for posting \_\_\_\_\_

2m, 11, 20.—T.



© 2021

Lloyd's Register  
 Foundation  
 W578-0245

Condition of beams

Up  
 1, A  
 ches.  
 ing i  
 hip.  
 12/11-  
 -17  
 of  
 se  
 Inche  
 in St  
 le  
 ne.  
 ang  
 ne  
 .44  
 0:46  
 4  
 56  
 m had  
 a bro  
 ske  
 1/2  
 +2/36  
 48  
 48  
 6  
 6  
 x.48  
 48  
 38  
 over  
 2  
 56  
 3 1/2  
 x 3 1/2 x 3 8