

1

Sent to Chief Surveyors 11.4.18.

Received from Chief Surveyors

VESSEL'S NAME Sheels MalanchaReport LibNo. 17274**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

✱ 100 A-1. (Steel)

2 DRs (Steel) 3" DR (Steel) in hot. Hold.


Cell DB 456' 23236. D.T. a 39'. 15036. FRT 1276. ART. 1206

FK. Intermediate BH in lower DR dispensed with 7 BH to upper DR.

1 BH to 2" DR only

Cen. Rlyds at CP. P 52' B 157' F 40'

Carrying oil fuel FP. above 150°F in DB & D.T.


 11.4.18


© 2020

Lloyd's Register
Foundation

W600 0080