

ks *Good* Inner Bottom Plating
Doing. Plates under Sounding Pipes *Good*
Engine Room Skylights
State if Tanks have been examined
W661-0035

S. Rabat.

Submitted a fee of £60 be charged
for the survey on the hull and £20.
for the survey on the machinery.

Sent

26/7/21

9 R R

13/4/21.

16 for Freight and
Assessment
J. W. B.
26/7/21

and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel was surveyed by ...